
2. 各部の名称と設定

2. Parts Names and Settings



No.	名称	内 容					
①	動作表示	LED名	確認内容				
	LED	PW	入力ユニット電源 ON により点灯				
	,	L RUN	入力ユニットがマスタ局と正常にデータ				
	}		交信して	いるかチェックする。			
	}		マスタ局から正常なデータを受信すると				
	,		き点灯、	き点灯、タイムオーバにより消灯する。			
				- タを受信することにより点灯する)			
		SD	データ送信により点灯				
		RD	2017	タにより点灯			
	}	L ERR.	伝送エラ	ー(CRC エラー)により点灯、			
	,		タイムオ	ーバにより消灯する。(RUNも			
			消灯)				
			局番設定	、伝送速度設定ミスにより点灯			
			(設定を修正し電源再投入により消灯)局				
			番設定、伝送速度設定が途中で変化した				
			ときERR点滅(RUNは点灯、ユニットは				
			電源立上げ時の局番設定および伝送速度				
			設定の条件で動作する)				
		0~F	- July o over the table				
		0~ [)~ F 入出力の ON/OFF 状態を表示 ON 状態で点灯、OFF 状態で消灯				
2	伝送速度		設定	伝送速度			
_	設定		0	156 kbps			
			1	625 kbps			
				2.5 Mbps			
		3		5 Mbps			
		4		10 Mbps			
	,	伝送速度設定スイッチは必ず0~4の範囲で設定し					
	L	てくだる					
3	局番設定			ットの局番は、必ず01~64の範			
	スイッチ	囲で設定してください。(*1)					
			X10" は、局番の 10 の位を設定します。				
		・"X1" は、局番の1の位を設定します。					

NO.	石外	N E		NO.	Item	Description			
0	動作表示	LED名	<u> </u>		1			Dname Confirmation details	
	LED	PW	入カユニ	ット電源 ON により点灯		status	PW	Turns on when input module power supply	
]	indicator		is turned on.	
1		L RUN				LEDs	L RUN	Check if the input module is communicating	
			交信しているかチェックする。			•		with the master station normally. Turns or	
			マスタ局から正常なデータを受信すると					when normal data is received from master	
İ			き点灯、タイムオーバにより消灯する。					station, and turns off when time is expired.	
			(正常なデータを受信することにより点灯する)					(Turned on by receiving normal data.)	
		SD	データ送信により点灯]		SD	Turns on when sending data.	
		RD	受信データにより点灯		1 1		RD		
		LERR.	. 伝送エラー(CRC エラー)により点灯、				LERR.	Turns on when transmission error (CRC	
] .			タイムオ	ーバにより消灯する。(RUNも				error) occurred, and turns off when time is expired. (RUN also turns off.)	
			消灯)					Turns on when station number setting o	
			局番設定	、伝送速度設定ミスにより点灯				transmission speed setting is incorrec	
			(設定を何	8正し電源再投入により消灯) 局				(turns off when the setting is corrected and	
]			番設定、	伝送速度設定が途中で変化した	1			power is restarted).	
			ときERR点滅(RUNは点灯、ユニットは		} }			ERR flashes when station number setting or transmission speed setting is changed	
			電源立上げ時の局番設定および伝送速度		[]			since startup. (RUN remains on. The	
			設定の条件で動作する)		1 1		l	module keeps operating with the same	
) [station number and transmission speed	
			<u> </u>					settings when the power was turned on.)	
		0~F	入出力の ON/OFF 状態を表示 ON 状態で点灯、OFF 状態で消灯				0 to F	0 to F Shows on/off status of I/O. Turns on wher on, turns off when off.	
2	伝送速度		設定	伝送速度	2	Trans-	Setting Transmission speed		
1	設定		0	156 kbps		mission		0 156 kbps	
			1	625 kbps		speed		1 625 kbps	
			2	2.5 Mbps]	setting		2 2.5 Mbps	
			3	5 Mbps				3 5 Mbps	
			4	10 Mbps				4 10 Mbps	
				ッチは必ず0~4の範囲で設定し	1	i		to set the transmission speed setting switches	
			てください。					e range of 0 to 4.	
3	局番設定	リモートI/O ユニットの局番は、必ず01~64の範		3	Station	Be sure to set the station numbers of remote I/O			
	スイッチ		囲で設定してください。(* 1) ・"X10" は、局番の 10 の位を設定します。			number settina	module within the range of 01 to 64. (* 1) "X10" sets the tens digit of the station number.		
				の10の位を設定します。 11の位を設定します。		switches		ets the units digit of the station number.	
4	端子台			、伝送、入出力信号の接続用端子	4	Terminal	A terminal block for connection to the input module		
"	V# 1 □	台です。				block	power supply, transmission and I/O signals.		
*1)	*1同番を重複して設定することはできません。								

Item

Description



AJ65BTB1-16D 形 CC-Link システムリモート入力ユニットユーザーズマニュアル AJ65BTB1-16D CC-Link System Remote Input Module User's Manual

● 安全上のご注意 ●

(ご使用前に必ずお読みください)

本製品のご使用に際しては、本マニュアルをよくお読みいただ くと共に、安全に対して十分に注意を払って、正しい取扱いをし ていただくようお願いいたします。

なお、この注意事項は本製品に関するもののみについて記載し たものです。シーケンサシステムとしての安全上のご注意に関し ては、CPU ユニットのユーザーズマニュアルを参照してください。 この●安全上のご注意●では、安全注意事項のランクを「危険」、 「注意」として区分してあります。

(!)危険

取扱いを誤った場合に, 危険な状況が起こ りえて、死亡または重傷を受ける可能性が 想定される場合。



取扱いを誤った場合に、危険な状況が起こ りえて、中程度の傷害や軽傷を受ける可能 性が想定される場合および物的損害だけの 発生が想定される場合。

なお, ▲ 注意に記載した事項でも、状況によっては重大な結果 に結びつく可能性があります。

いずれも重要な内容を記載していますので必ず守ってください。 本マニュアルは必要なときに読めるように大切に保管すると共 に、必ず最終ユーザまでお届けいただくようにお願いいたします。

【設計上の注意事項】

(1) 危険

- データリンクが交信異常になったとき、交信異常局は次のような状態になり 交信状態情報を使って、システムが安全側に働くようにシーケンスプログラ ム上でインタロック回路を構成してください。 誤出力、誤動作により事故の恐れがあります
- リモート 1/0 局からの入力は、全点 OFF します。 ● リモート I/O ユニットの故障によっては、入力が ON 状態または OFF 状態に なることがあります。重大な事故につながるような入力信号については、外 部で監視する回路を設けてください。

⚠注 意

- ユニットは、CPU ユニットユーザーズマニュアル記載の一般仕様の環境で使 用してください。 一般仕様の範囲以外の環境で使用すると、感電、火災、誤動作、製品の損傷
- あるいは劣化の原因になります。 ● 制御線や通信ケーブルは、主回路や動力線などと束線したり、近接したりし ないでください。100mm以上を目安として離してください。 ノイズにより、誤動作の原因になります。

【取付け上の注意事項】

▲注 意

- ユニットの導電部分には直接触らないでください。 ユニットの誤動作、故障の原因になります。
- ユニットは、DIN レールまたは取付けネジにて、確実に固定し、取付けネジ は規定トルク範囲内で確実に締め付けてください。

ネジの締付けがゆるいと、落下、短絡、誤動作の原因になります。 ネジを締め過ぎると、ネジの破損による落下、短絡の原因になります。

【配線上の注意事項】

 (I) 危 険

- 配線作業などは、必ずシステムで使用している外部供給電源を全相遮断して から行ってください。全相遮断しないと、感電あるいは製品の損傷の恐れが
- 取付け、配線作業などの後、通電、運転を行う場合は、必ず製品に付属の端 子カバーを閉めてください。 端子カバーを閉めないと、感電の恐れがあります。

本マニュアルは再生紙を使用しています。

SAFETY PRECAUTIONS

(Read these precautions before using.)

When using this equipment, thoroughly read this manual. Also pay careful attention to safety and handle the module properly.

These precautions apply only to this equipment. Refer to the CPU module user's manual for a description of the PLC system safety precautions.

These SAFETY PRECAUTIONS classify the safety precautions into two categories: "DANGER" and "CAUTION".



Procedures which may lead to a dangerous condition and cause death or serious injury if not carried out properly.



Procedures which may lead to a dangerous condition and cause superficial to medium injury, or physical damage only. if not carried out properly.

Depending on circumstances, procedures indicated by ${\underline{\bigwedge}}$ CAUTION may also result in to serious results.

In any case, it is important to follow the directions for usage.

Store this manual in a safe place so that you can take it out and read it whenever necessary. Always forward it to the end user.

(0608) MEE

[DESIGN PRECAUTIONS]

<!>DANGER

- When a communication error occurs in the data link, the communication error station will be in the following condition. Configure an interlocking circuit in a sequence program using the communication status information so that the safety of the overall system is always maintained.
 - Accident may occur due to output error or malfunction. Input points from remote I/O station will be all off.
- Input could be on or off when there is trouble in the remote I/O modules. So build an external monitoring circuit that will monitor any input signals that could cause serious trouble.

♠ CAUTION

- Use each module in an environment as specified in the "general specification" in the CPU module user's manual. Usage of the module outside the general specification range may cause electric shock, fire, malfunction, product damage or deterioration.
- Do not have control cables and communication cables bundled with or placed near by the main circuit and/or power cables. Wire those cables at least 100mm(3.94 inch) away from the main circuit and/or power cables. If may cause malfunction due to noise interference

[INSTALLATION PRECAUTIONS]

♠CAUTION

- Do not directly touch the module's conductive parts.
- Doing so could cause malfunction or trouble in the module.
- Tighten the module securely using DIN rail or installation screws within the specified torque range. Loose terminal screws may cause a short circuit or erroneous operation. If the terminal screws are too tight, it may cause falling, short circuit or erroneous operation due to damage of the screws

[WIRING PRECAUTIONS]

<!>DANGER

- Completely turn off the externally supplied power used in the system when installing or placing wiring. Not completely turning off all power could result in electric shock or damage to the product.
- Make sure to close the terminal cover shipped with the product when starting the power supply or operation after installation, wiring, etc. If terminal cover is not closed an electric shock may result.

Printed in Japan on recycled paper.

∧注 意

- FG 端子はシーケンサ専用のD種接地(第三種接地)以上で必ず接地を行ってください。感電、誤動作の恐れがあります。
- ◆ 空き端子ネジは必ず締付けトルク範囲(42~50N·cm)で締付けてください。 圧着端子と短絡する原因になります。
- ユニットの配線は、製品の定格電圧および端子配列を確認した上で正しく行ってください。
 定格と異なった電源を接続したり、誤配線すると、火災、故障の原因になり
- ・ 端子ネジの締付けは、規定トルク範囲内で行ってください。・ 端子ネジの締付けがゆるいと、火災や誤動作の原因になります。
- 端子ネジを締め過ぎると、ネジの破損による短絡、誤動作の原因になります。 ■ ユニット内に、切粉や配換スなどの異物が入らないように注意してください、 火災、故腔、誤動作の原因になります。
- ユニットに接続する電線やケーブルは、必ずダクトに納める。またはクランプによる固定処理を行ってください。ケーブルをダクトに納めなかったり、クランプによる固定処理をしていないと、ケーブルのふらつきや移動、不注意の引っ張りなどによるユニットやケーケーブルのふらつきや移動、不注意の引っ張りなどによるユニットやケーブルのふらつきや移動、不注意の引っ張りなどによるユニットやケーブルのふらつきできない。
- ーブルの破損、ケーブルの接触不良による誤動作の原因となります。 ● 制御線と通信ケーブルは束線したり、近接したりしないでください。 ノイズにより、誤動作の原因になります。
- → 1 へにより、原料リドリのには少りより。 ・ ユニットに接続された通信ケーブルや電源ケーブルを取り外すときは、ケーブル部分を手に持って引っ張らないでください。 コネクタ付きのケーブルは、ユニットに接続している部分のコネクタを手で 持って取り外してください。コネクタなしのケーブルは、ユニットに接続し
- ユニットに接続された状態でケーブルを引っ張ると、ユニットやケーブルの破禍、ケーブルの接続不良による誤動作の原因となります。

ている部分のネジを緩めてから取り外してください。

【立上げ・保守時の注意事項】

①危 険

- 通電中に端子に触れないでください。 感電の原因になります。
- 清掃,端子ネジ、ユニット取付けネジの増し締めは、必ずシステムで使用している外部供給電源を全相遮断してから行ってください。全相遮断しないと、ユニットの枚連や誤動作の原因になります。

▲注 意

- ユニットの分解,改造はしないでください。
 故障、誤動作、ケガ、火災の原因になります。
- ユニットは落下させたり、強い衝撃を与えないでください。
 ユニットの破損の原因になります。
- ユニットの絵への取付け、取外しは必ずシステムで使用している外部供給電源を全相遮断してから行ってください。全相遮断しないと、ユニットの故障や暗動作の原因になります。
- 端子台の着脱は、製品ご使用後、50回以内としてください。
 (JIS B 3502 準拠)
- ユニットに触れる前には、必ず接地された金属などに触れて、人体などに帯電している静電気を放電してください。 静電気を放電しないと、ユニットの故障や揺動作の原因になります。

【廃棄時の注意事項】

● 製品を廃棄するときは、産業廃棄物として扱ってください。

1. 仕様

1 - 17 4%				
Ij	目	内容		
入力点数		16点		
絶縁方式		フォトカプラ絶縁		
定格入力電	圧	DC24V		
定格入力電	流	約7mA		
使用電圧範	囲	DC19.2~28.8V(リップル率 5%以内)		
最大同時入	力点数	100%		
ON 電圧/	ON 電流	14V以上/3.5mA以上		
OFF 電圧/	OFF 電流	6V以下/1.7mA以下		
入力抵抗		約 3.3kΩ		
応答時間	OFF → ON	10msec 以下		
	ON → OFF	10msec 以下		

^CAUTION

- Always ground the FG terminal.
 There is a risk of electric shock or malfunction.
- Be sure to tighten any unused terminal screws within a tightening torque range (42 to 50N cm).
 Failure to do so may cause a short circuit due to contact with a solderless
- terminal.

 Use applicable solderless terminals and tighten them with the specified torque.
- If any solderless spade terminal is used, it may be disconnected when the terminal screw comes loose, resulting in failure.
- Perform correct wiring for the module according to the product's rated voltage and terminal arrangement. Connecting to a power supply different from rating or miss-wiring may cause fire and/or product failure.
- Fix terminal screws securely within the regulated torque. Loose terminal screws may cause fire and/or malfunction.
 If the terminal screws are too tight, it may cause short circuit or erroneous
- operation due to damage of the screws.

 Make sure foreign objects do not get inside the module, such as dirt and wire chins. It may cause fire product failure or malfunction.
- Be sure to fix the wires or cables by ducts or clamps when connecting them
 to the module. Failure to do so may cause damage of the module or the
 cables due to accidental pull or unintentional shifting of the cables, or
 malfunctions due to poor contact of the cable.
- Do not install the control lines together with the communication cables, or bring them close to each other. Failure to do so may cause malfunctions due to noise
- When disconnecting a communication or power supply cable from the module, do not pull on the cable itself. Disconnect cables not fitted with a connectors by holding and pulling the cable connector. Disconnect cables not fitted with a connector by removing the screws from the part connected to the module can cause damage to the module or cable, or malfunction due to cable connection faults.

[STARTING AND MAINTENANCE PRECAUTIONS]

DANGER

- Do not touch terminals when the power is on. Doing so could cause an electric shock.
- Switch off all phases of the externally supplied power used in the system when cleaning the module or retightening the terminal or module mounting screws. Not doing so could result in electric shock.

∴CAUTION

- Never try to disassemble of modify module. It may cause product failure, malfunction, fire or cause injury.
- Do not drop or apply any strong impact to the module. Doing so may damage the module.
- Completely turn off the externally supplied power used in the system before mounting or removing the module to/from the panel. Not doing so could result in damage to the product.
- Mounting/removing the terminal block is limited to 50 times after using a product. (IEC61131-2-compliant)
- Always make sure to touch the grounded metal to discharge the electricity charged in the electricity charged in the body, etc., before touching the module.
 Failure to do so may cause a failure or malfunctions of the module.

[DISPOSAL PRECAUTIONS]

∴CAUTION


When disposing of this product, treat it as industrial waste.

1. Specification

Item		Description		
Number of input points		16 points		
Isolation me	thod	Photocoupler		
Rated input voltage		24 VDC		
Rated input current		Approx. 7 mA		
Operating voltage range		19.2 to 28.8 VDC (ripple ratio: within 5%)		
Max. simultaneous ON		100 %		
input points				
ON voltage/ON current		14 V or higher/3.5 mA or higher		
OFF voltage/OFF curren		6 V or lower/1.7 mA or lower		
Input resistance		Approx. 3.3 kΩ		
Response time	OFF → ON	10 msec or lower		
	ON → OFF	10 msec or lower		

		 		
項目		内容		
コモン方式		16 点 1 コモン (1 線式端子台)		
入力形式		シンク、ソース共用タイプ		
占有局数		1局		
I/Oユニット電源	電圧	DC15.6~28.8V(リップル率 5%以内)		
	電流	60mA以下(TYP.DC24V 時)		
ノイズ耐量		DC タイプのノイズ電圧 500Vp-p ノイズ幅 1μs, ノイズ周波数 25~60Hz の ノイズシミュレータによる		
耐電圧		DC 外部端子一括 アース間 AC500V 1 分間		
絶縁抵抗		DC 外部端子一括 アース間 DC500V 絶縁抵抗計にて 10MΩ 以上		
質量		320g		
外部接続方式		27点端子台		
		(M3.5 ネジ締付けトルク 59~88N·cm)		
		伝送回路, ユニット電源端子含む		
適合電線サイズ		0.75~2mm²		
ユニット取付けネ	ジ	M4×0.7mm×16mm以上ネジ		
		(締付けトルク範囲 78~118N·cm)		
		DIN レールでの取付けも可能		
適用 DIN レール		TH35-7.5Fe, TH35-7.5Al, TH35-15Fe (JIS C 2812 に準拠)		
適合圧着端子		RAV 1.25-3.5 (JIS C 2805 に準拠) RAV 2-3.5		

Item		Description		
Common method		16 points/common (1-wire terminal block)		
Input form		Sink/source loading shared type		
Number of stations	occupied	1 station		
I/O module	Voltage	15.6 to 28.8 VDC (ripple rate : within 5 %)		
power supply	Current	60 mA or lower (when TYP.24 VDC)		
Noise durability		DC type noise voltage 500Vp-p, Noise width 1µs, Noise frequency 25 to 60Hz (noise simulator condition)		
Withstanding volta	ge	500 VAC for 1 minute between all DC external terminals together and ground		
Insulation resistance	e	10 MΩ or higher, measured with a 500 VDC insulation resistance tester		
Weight		320 g (0.7 lb)		
External wiring sys	tem	27-point terminal block (M3.5 screws tightening torque: 59 to 88 N·cm) including transmission circuit, and module power supply terminal		
Applicable wire siz	e	0.75 to 2 mm ²		
Module installation	screw	M4 (0.16) × 0.7 mm (0.03) × 16 mm (0.63) screws (tightening torque range 78 to 118 N·cm) DIN rails can be used for installation		
Applicable DIN rail		TH35-7.5Fe, TH35-7.5Al, TH35-15Fe (conforming to IEC 60715)		
Applicable solderless terminal		RAV 1.25-3.5 (JIS C 2805 conforming) RAV 2-3.5		



外部接続 (External connection)

端子番号	信号名	端子番号	信号名			
Terminal number	Signal name	Terminal number	Signal name			
TB1	DA	TB15	X7			
TB2	TB2 DB		сом			
TB3	TB3 DG		NC			
TB4	SLD	TB18	X8			
TB5	+24V	TB19	Х9			
TB6	₽FG	TB20	XA			
TB7	24G	TB21	XB			
TB8	X0	TB22	XC			
TB9	X1	TB23	XD			
TB10	X2	TB24	XE			
TB11	Х3	TB25	XF			
TB12	X4	TB26	СОМ			
TB13	TB13 X5		NC			
TB14	X6					